WDMI-37 NCE Pro Cab Wi-Fi Interface Module

Compatibility, Firmware Issues and Workarounds

This document is online at http://www.wifitrax.com/manuals/WDMI-37/WDMI-37-known-issues.pdf.

Please see our website for information on our limited warranty.

WifiTrax Model Science

www.wifitrax.com

Known Firmware Issues

Number	Description	F/W Version found	Work Around Prior to Fix	F/W Version Fixed	Comments Relating to fix
1	When operating with DCC on the track, the WDMI-37 does not respond to commands sent to long DCC addresses. This occurs even when the DCC address of the attached DCC Decoder has a long value. Locos with the decoder set to a long DCC address operate correctly when commands are received by the WDMI-37 via Wi-Fi.	1.2.3	Either use a short DCC address or use Wi-Fi only to control your loco.		